



Performing Scan Disk on a 3Z Series Printer

Performing Scandisk on 3Z Printer

These are the instructions to run Scandisk on the hard disk.

- From the Windows CE screen, bring up the start button by pressing the bottom left corner of the screen.
- Press **Start>> Settings>> Control Panel**. (Fig. 1)
- Double click on the **Storage Manager** Icon. (Fig. 2)
- Press **Part01**. (Fig. 3)
- Press **Dismount**. (Fig. 3)
- Press the **Properties** Icon Under the Delete button (**WARNING: DO NOT PRESS THE DELETE ICON**). The button is slightly hidden. You will not be able to read the words. (Fig. 4)
- Press only the **Scan** Icon. (Fig. 5)
- Press the **Start** button. Note the information at the end of the process. (Fig. 6)
- Press the **OK** button. (Fig. 7)
- Press the **Mount** button. (Fig. 8)
- Reboot the printer.



Fig.1




Fig. 2



Fig. 3



Fig. 4



Performing Scan Disk on a 3Z Series Printer




Fig. 5



Fig. 6



Fig. 7



Fig. 8